

### Electrically heated stationary pressure washers

The SOLAR BOOSTER range offers low heating and running costs combined with a design that is easy to use and service. The onboard PCB enables the machine to be customised with factory mounted options. The SOLAR BOOSTER E line is equipped a large 119 litre heating tank and can be produced in several heating sizes frm 18kW to 54 kW depending upon the temperature requirements and available electrical network. Electrical heating is pollution free. A feeder pump ensures that the pump can be fed with water up to 85 <sup>o</sup>C. Immediate hot water is thus present at first activation of trigger.

- Brass cylinder head
- Expandable control technology with PLC, customisation through options
- Automatic diagnosis and fault finding
- Pollution free, heating system
- Galvanised and powder coated steel frame and cabinet
- Reduced running and service costs
- Large 119 L heating tank for excellent heating capacity
- Available up to 54 kW heating
- C3 longlife pump with 4 ceramic pistons
- MMO - Multiple Machine Option - OPTIONAL



Picture shown may not represent model quoted

Electrical powered stationary heating for maximum efficiency in the automotive, industrial, food and shipping sectors. Electrical heating is exhaust gas and pollution free.

- Standard equipment
- Standard equipment

Model	SH SOLAR 7P-135/875 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 440/3/60 EXPT
Ref. no.	107370260	107370270	107370272

#### PRODUCT FEATURES

C3 4-ceramic piston pump	•	•	•
Electrical heating system	•	•	•
Brass cylinder head	•	•	•
Automatic start/stop	•	•	•
1450 rpm motor	•	•	
Galvanised steel frame	•	•	•
PLC and expandable control electronics	•	•	•
Electrical heating tank 119 l	•	•	•
Auto fault finding	•	•	•
Water brake tank	•	•	•



## Electrically heated stationary pressure washers

Model	SH SOLAR 7P-170/1200 E36 400/3/50 EU	SH SOLAR 7P-170/1200 E54 400/3/50 EU
Ref. no.	107370274	107370276

## PRODUCT FEATURES

C3 4-ceramic piston pump	•	•
Electrical heating system	•	•
Brass cylinder head	•	•
Automatic start/stop	•	•
1450 rpm motor	•	•
Galvanised steel frame	•	•
PLC and expandable control electronics	•	•
Electrical heating tank 119 l	•	•
Auto fault finding	•	•
Water brake tank	•	•

Technical specifications	SH SOLAR 7P-135/875 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 440/3/60 EXPT
Sound pressure level (dB(A))	92	92	97
Pump pressure (bar/MPa)	135/13.5	170/17	170/17
Cleaning impact (kg/force)	3.8	5.8	5.8
Power consumption (kW)	5.8 + 18	7.5 + 18	7.5 + 18
Voltage/phase/frequency/current (V/~/HZ/A)	400/3/50/36	400/3/50/39	440/3/60
Water flow Qmax/Qiec (l/h)	875/810	1200/1110	1200/1110
Water temperature, Delta T at full flow (°C)	19	14	14
Max temperature (C)	85	85	85
Nozzle size	.0530	.0680	.0680
Max inlet temperature (°C)	85	85	85
Min. inlet water pressure at full flow (bar)	1	1	1
Ceramic pistons	4	4	4
Length x width x height (MM)	670x900x1077	670x900x1077	670x900x1077
Weight (KG)	150	155	158







Technical specifications	SH SOLAR 7P-170/1200 E36 400/3/50 EU	SH SOLAR 7P-170/1200 E54 400/3/50 EU
Sound pressure level (dB(A))	92	92
Pump pressure (bar/MPa)	170/17	170/17
Cleaning impact (kg/force)	5.8	5.8
Power consumption (kW)	7.5 + 36	7.5 + 54
Voltage/phase/frequency/current (V/~/HZ/A)	400/3/50/65	400/3/50/91



Electrically heated stationary pressure washers










Technical specifications	SH SOLAR 7P-170/1200 E36 400/3/50 EU	SH SOLAR 7P-170/1200 E54 400/3/50 EU
Water flow Qmax/Qiec (l/h)	1200/1110	1200/1110
Water temperature, Delta T at full flow (°C)	28	42
Max temperature (C)	85	85
Nozzle size	.0680	.0680
Max inlet temperature (°C)	85	85
Min. inlet water pressure at full flow (bar)	1	1
Ceramic pistons	4	4
Length x width x height (MM)	670x900x1077	670x900x1077
Weight (KG)	155	156

● Standard equipment, ○ Supplementary accessories, □ Mountable equipment

Accessories	Ref. no.	Min. required	SH SOLAR 7P-135/875 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 440/3/60 EXPT
<b>Standard Nozzle 50° 1/8" NPT</b>					
 HP NOZZLE 50070 1/8	5007	0		○	○
<b>High Pressure Male Coupling</b>					
 ADAPTOR 3/8 INCH MALE FOR HOSE	6401067	1	○	○	○
 ADAPTOR KEW GUN TO WAP ACCESS.	66161	0	○	○	○
GARDENA COUPLING HOSE END 1/2 BULK	1608629	0	○	○	○
 GEKA COUPLING HOSE END 3/4	1311	0	○	○	○
 LP NIPPLE F. Q.-COUPLING 3/4IN	1600659	0	○	○	○
 NITO COUPLING HOSE END 1	1604669	0	○	○	○
<b>Abrasive Blasting</b>					














## Electrically heated stationary pressure washers







Accessories		Ref. no.	Min. required	SH SOLAR 7P-135/875 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 440/3/60 EXPT
	ARMEX-POWDER	5218617	1	○	○	○
	BORONCARBIDE FLAT NOZZLE VSB	6400379	0	○	○	○
	LANCE SOFTBLASTING W. NOZZLE 05	6401233	1	○		
	LANCE WITH RUBBER FLAT NOZZLE 06	6401365	1	○	○	○
	NOZZLE FOR WSB - FLAT RUBBER 10 PC.	6402317	0	○	○	○
	SAND PLUGGER AND HOSE VSB	6400375	1	○	○	○
	SUPER BLAST 25KG	8379	1	○	○	○
<b>Detergent</b>						
	ALTO ACIDO 10 L	81204	1	○	○	○
	ALTO ACTIVE WAX 10 L	81177	1	○	○	○
	ALTO ALLOSIL 10 L	81237	1	○	○	○
	ALTO ANTI-STONE 10 L	80919	1	○	○	○
	ALTO COMBI ACTIVE 10L	81172	1	○	○	○
	ALTO INTENSIVE 10 L	81137	1	○	○	○














## Electrically heated stationary pressure washers

Accessories		Ref. no.	Min. required	SH SOLAR 7P-135/875 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 440/3/60 EXPT
	ALTO J 25 MULTI 10 L	80923	1	○	○	○
	ALTO RIMTOP 10 L	80935	1	○	○	○
	ALTO SAPPHIRE 10 L	81180	1	○	○	○
	ALTO STONE-EX 10 L	81191	1	○	○	○
	ALTO SUPERPLUS 10 L	81170	1	○	○	○
	ALTO UNIVERSAL 10 L	80930	1	○	○	○
	ANTI-STONE SET-6X1 L	8466	1	○	○	○
	AUTO ACTIVE 10 L	81136	1	○	○	○
<b>Brush Washing</b>						
	BRUSH INSERT	10356	1	○	○	○
	WASH BRUSH - ERGO - UNIVERSAL LANCE	14202	1	○	○	○
	WASH BRUSH L1550 MM	6400088	1	○	○	○

## Electrically heated stationary pressure washers











Accessories		Ref. no.	Min. required	SH SOLAR 7P-135/875 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 440/3/60 EXPT
	WASH BRUSH L2350 MM	6400087	1	○	○	○
<b>Special Nozzle</b>						
	NOZZLE FOR LONG LANCEJET 6-7 M	2802696	0	○	○	○
	NOZZLE PROTECTION CAP PA	18430	1	○	○	○
<b>Stationary Equipment</b>						
	ACCESSORY FROST PROTECTION DELUXE	107370955	1	○	○	○
	ACCESSORY FROST PROTECTION STANDARD	107370954	1	○	○	○
	COINBOX 0.5 EUR	54328	1	○	○	○
	COINBOX 0.5 EUR INCL DETERGENT	54332	1	○	○	○
	COINBOX 1EUR	54329	1	○	○	○
	COINBOX 1EUR INCL DETERGENT	54333	1	○	○	○
	COINBOX TOKEN	54330	1	○	○	○
	COINBOX TOKEN INCL DETERGENT	54334	1	○	○	○
	MAINS CUT OFF BUTTON	29277	1	○	○	○
	OPTION 1XDETERGENT SOLAR	107370952	1	○	○	○
	OPTION 2XDETERGENT SOLAR	107370953	1	○	○	○
	OPTION AUTOMATIC PRESSURE RELIEF SOLAR	107370966	1	○	○	○
	OPTION NO-SCALE SOLAR	107370958	1	○	○	○
	OPTION REMOTE CONTROL 4 BUTTONS	107340913	1	○	○	○
	OPTION REMOTE CONTROL 5 BUTTONS	107340914	1	○	○	○
	OPTION WATER INLET SECURITY	107340910	1	○	○	○
	REMOTE CONTROL BOXES 2 BUTTONS	107340911	1	○	○	○

## Electrically heated stationary pressure washers












Accessories		Ref. no.	Min. required	SH SOLAR 7P-135/875 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 440/3/60 EXPT
	REMOTE CONTROL BOXES 3 BUTTONS	107340912	1	○	○	○
<b>Drain and Pipe Cleaning</b>						
	DRAIN CLEANER 05 20M HOSE	6401266	1	○		
	DRAIN CLEANER 06 20M HOSE	6401268	1	○	○	○
	DRAIN NOZZLE 05 3/8	2800084	0	○		
	DRAIN NOZZLE 06. 3/8	2800894	1		○	○
	PIPE CLEANING HOSE 4X10M	301002490	1	○		
	PIPE CLEANING HOSE 4X20M	301002491	1	○		
	PIPE CLEANING HOSE 4X30M	301002492	1	○		
	PIPE CLEANING NOZZLE 1/8INC IG DN4	46921	1	○		
	PIPE CLEANING ROTATY NOZZLE 1/8INC IG DN	46918	0	○		
<b>Filter Pressure Washer</b>						
	CARTRIDGE FILTER REPLACEM. 50 uM	1104041	1	○	○	○
	FILTER - WATER/SAND. SS	4601431	1	○	○	○














## Electrically heated stationary pressure washers

Accessories		Ref. no.	Min. required	SH SOLAR 7P-135/875 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 440/3/60 EXPT
	FILTER CARTRIDGE 1 1/2	4602439	1	○	○	○
	SAND FILTER 50MICRON UNIVERSAL	1604461	1	○	○	○
<b>Non Blacking High Pressure Hose, DN10</b>						
	20 M 2 WIRE HOSE 3/8 FOOD	1401991	1	○	○	○
	25 M 2 WIRE HOSE 3/8 FOOD	1402007	1	○	○	○
	30 M 2 WIRE HOSE 3/8 FOOD	1402015	1	○	○	○
	HOSE DN10 10 M 2W 3/8X3/8 GRAU-FOOD	6101767	1	○	○	○
	HOSE DN10 15 M 2W 3/8X3/8 GRAY-FOOD	1401983	1	○	○	○
<b>High Pressure Hose, DN10</b>						
	2 M 2 WIRE HOSE 3/8 DN10	1402924	1	○	○	○
	3 M 2 WIRE HOSE 3/8 DN10	1402932	1	○	○	○
	5 M 2 WIRE HOSE 3/8 DN10	1402940	1	○	○	○
	25 M 2 WIRE HOSE 3/8 DN10	1402080	1	○	○	○

## Electrically heated stationary pressure washers











Accessories		Ref. no.	Min. required	SH SOLAR 7P-135/875 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 440/3/60 EXPT
	30 M 2 WIRE HOSE 3/8 DN10	1402098	1	○	○	○
	50 M 2 WIRE HOSE 3/8 DN10	1402759	1	○	○	○
	HOSE DN10 10 M 2W 3/8X3/8 INCH	6101766	1	○	○	○
	HP HOSE 3/8INCH 1M DN10. COMPL.	1402916	1	○	○	○
	HP HOSE DN10 150DEG L15000mm	1402064	1	○	○	○
	M 20 WIRE HOSE 3/8 DN10	1402072	0	○	○	○
<b>High Pressure Hose, DN8</b>						
	10 M 1 WIRE HOSE 5/16 DN8	1405569	1	○		
	HOSE DN8 1 WIRE 10M W.ERGO FEMALE COUPL.	101405770	1	○		
	HOSE DN8 1 WIRE 15M W.ERGO FEMALE COUPL.	301001100	1	○		
	HOSE DN8 1 WIRE 20M W.ERGO FEMALE COUPL.	301001101	1	○		
	HOSE DN8 20 M 1W - 3/8X3/8	1405666	1	○		
<b>Ergo System Coupling and Adapter</b>						

## Electrically heated stationary pressure washers


Accessories		Ref. no.	Min. required	SH SOLAR 7P-135/875 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 440/3/60 EXPT
	COUPLING - FEMALE/Q-COUPPL 3/8 INCH	106402075	1	○	○	○
	ERGO COUPLING KIT	101119496	1	○	○	○
	HIGH PRESSURE COUPLINGS KIT	101119499	1	○	○	○
	Nippel F. Q-COUPPL. 3/8 INCH	1600493	1	○	○	○
	NIPPLE F/QUICK COUPLING 3/8 SS	1603101	1	○	○	○
	NIPPLE FOR SPRAY LANCE STAN.L	1609325	0	○	○	○
	PACKING RING 23.8X17.2X2 3/8 INCH St-NBR	1801075	0	○	○	○
<b>High Pressure Hose, DN12</b>						
	10 M 2 WIRE HOSE 1/2 DN12	4810219	0	○	○	○
	15 M 2 WIRE HOSE 1/2 DN12	4810213	0	○	○	○
	20 M 2 WIRE HOSE 1/2 DN12	4810214	0	○	○	○
<b>Brush Rotary</b>						
	BRISTLE. LONG	6401431	0	○	○	○
	NYLON. BRISTLE FOR ROTARY	6401432	0	○	○	○



## Electrically heated stationary pressure washers











Accessories		Ref. no.	Min. required	SH SOLAR 7P-135/875 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 440/3/60 EXPT
	ROTARY BRUSH 055 1700MM	6400019	1	○		
	ROTARY BRUSH 055 L800 MM	6400018	1	○		
	ROTARY BRUSH 065 L1700 MM	6400016	1		○	○
<b>Special Lance</b>						
	CURVED LANCE L1090 MM	6402016	1	○	○	○
	LANCE SINGLE 1500MM W/O NOZZLE	6401193	1	○	○	○
	UNDER CARRIAGE WASHER 40065	6400036	1	○	○	○
<b>Hose Reel</b>						
	CLEANING TROLLEY SS W/HOOSE REEL FOAM IN	6401094	1	○	○	○
	HOSE TROLLEY UP TO 50 M 3/8	6400170	1	○	○	○
<b>Injector and Foam Sprayer</b>						
	03 INJECTOR COMPLETE	6401247	1		○	○
	DETERGENT BOTTLE 2.5 L	107141635	0	○	○	○
	DETERGENT TANK W.SAFETY CAP - 2.5 LTR.	106403162	0	○	○	○

## Electrically heated stationary pressure washers

Accessories		Ref. no.	Min. required	SH SOLAR 7P-135/875 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 440/3/60 EXPT
	EXTENSION HOSE 30 CM WITH ERGO COUPLINGS	301001311	0	○	○	○
	FOAM INJECTOR AGRESSIVE LQDS	6401245	1	○	○	○
	FOAM INJECTOR W BYPASS	6401242	1	○	○	○
	FOAM INJECTOR W BYPASS S. S	6401243	1	○	○	○
	FOAM INJECTOR STANDARD	6401244	1	○	○	○
	FOAM LANCE COMPLETE L600 MM	6404368	1	○	○	○
	FOAM LANCE COMPLETE L1200 MM	6404369	1	○	○	○
<b>Spray Gun</b>						
	ERGO 2000 STANDARD W. HOSE SWIVEL	106403122	1	○	○	○
	REP. KIT SWIVEL JOINT	101119484	0	○	○	○
	SIDE BAR COMPL.	106402110	1	○	○	○
	SPRAY HANDLE W. SWIVEL LOCK	106402190	1	○	○	○
<b>Tornado Nozzle with Indication Ring</b>						
	NOZZLE 0530 INDICATION RING RED	101119742	1	○		













## Electrically heated stationary pressure washers




Accessories		Ref. no.	Min. required	SH SOLAR 7P-135/875 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 440/3/60 EXPT
	NOZZLE 0680 INDICATION RING GREY	101119747	1		○	○
	NOZZLE PROTECTION F. TORNADOL.	106402425	1	○	○	○
<b>Short Lance</b>						
	DOUBLE LANCE W/O NOZZLE 90MM	106402150	1	○	○	○
	SINGLE LANCE W/O NOZZLE 90MM	106402151	1	○	○	○
<b>FlexoPower Lance</b>						
	FLEXOPOWER HOUSE F.NZ 1/8 OUTS. THREAD	63251	0	○	○	○
	FLEXOPOWER PLUS 960 BEND W/O NOZZLE	106402282	1	○	○	○
	FLEXOPOWER PLUS 990 BEND W/O NOZ.	106402281	1	○	○	○
<b>Tornado Lance</b>						
	TORNADO PLUS 630 STRAIGHT W/O NOZZLE	106403013	1	○	○	○
	TORNADO PLUS 1000 BEND W/O NOZZLE	106403011	1	○	○	○
	TORNADO PLUS 1120 BEND W/O NOZZLE	106403010	1	○	○	○
	TORNADO PLUS 2080 BEND W/O NOZZLE	106403012	1	○	○	○
<b>Universal Lance</b>						








## Electrically heated stationary pressure washers

Accessories		Ref. no.	Min. required	SH SOLAR 7P-135/875 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 440/3/60 EXPT
	UNIVERSAL PLUS 650 W/O NOZZLE STRAIGHT	106403032	1	○	○	○
	UNIVERSAL PLUS 1080 W/O NOZZ STRAIGHT	106403033	1	○	○	○
	UNIVERSAL PLUS 1560 W/O NOZZLE STRAIGHT	106403031	1	○	○	○
	UNIVERSAL PLUS 2060 W/O NOZZLE STRAIGHT	106403030	1	○	○	○
	UNIVERSAL PLUS LANCE 940 BEND W/O NOZZ	106403036	1	○	○	○
	UNIVERSAL PLUS LANCE 1080 BEND W/O NOZZ	106403035	1	○	○	○
	UNIVERSAL PLUS LANCE 1230 BEND W/O NOZZL	106403034	1	○	○	○
<b>PowerSpeed Vario Lance</b>						
	POWERSPEED VARIO PLUS 1090 BEND 0530	106403094	1	○		
	POWERSPEED VARIO PLUS 1090 BEND 0680	106403096	1		○	○
<b>Surface Cleaning Rotary</b>						
	HYDROSCRUB P400 W/O NOZZLES	106403157	0	○	○	○
	HYDROSCRUB P500M Ø500 W/WHEELS W/O NOZZL	106403159	0	○	○	○
	HYDROSCRUB S500 Ø500 W/O NOZZLES	106403158	0	○	○	○
<b>High Pressure Female Coupling</b>						
	ADAPTER KEW QUICK COUPLING FEMALE 3/8	66160	0	○	○	○

## Electrically heated stationary pressure washers











Accessories		Ref. no.	Min. required	SH SOLAR 7P-135/875 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 400/3/50 EU	SH SOLAR 7P-170/1200 E18 440/3/60 EXPT
	ADAPTER WAP GUN COUPLING FEMALE M21X1.5	66162	0	○	○	○
	COUPLING GEKA FEMALE - INT THREAD 3/4 IN	1718	0	○	○	○
<b>Hose and Connection</b>						
	NILFISK BA VALVE COMP. GEKA	106411179	0	○	○	○
	NILFISK BA VALVE COMP. NITO	106411178	0	○	○	○
	NILFISK BA VALVE WO COUPLER	106411184	0	○	○	○
	WATER INLET HOSE 3/4 P/	6465	0	○	○	○

● Standard equipment, ○ Supplementary accessories, □ Mountable equipment












Accessories		Ref. no.	Min. required	SH SOLAR 7P-170/1200 E36 400/3/50 EU	SH SOLAR 7P-170/1200 E54 400/3/50 EU
<b>Standard Nozzle 50° 1/8" NPT</b>					
	HP NOZZLE 50070 1/8	5007	0	○	○
<b>High Pressure Male Coupling</b>					
	ADAPTOR 3/8 INCH MALE FOR HOSE	6401067	1	○	○
	ADAPTOR KEW GUN TO WAP ACCESS.	66161	0	○	○
	GARDENA COUPLING HOSE END 1/2 BULK	1608629	0	○	○
	GEKA COUPLING HOSE END 3/4	1311	0	○	○
	LP NIPPLE F. Q.-COUPLING 3/4IN	1600659	0	○	○










## Electrically heated stationary pressure washers

Accessories		Ref. no.	Min. required	SH SOLAR 7P-170/1200 E36 400/3/50 EU	SH SOLAR 7P-170/1200 E54 400/3/50 EU
	NITO COUPLING HOSE END 1	1604669	0	○	○
<b>Abrasive Blasting</b>					
	ARMEX-POWDER	5218617	1	○	○
	BORONCARBIDE FLAT NOZZLE VSB	6400379	0	○	○
	LANCE SOFTBLASTING W. NOZZLE 05	6401233	1		
	LANCE WITH RUBBER FLAT NOZZLE 06	6401365	1	○	○
	NOZZLE FOR WSB - FLAT RUBBER 10 PC.	6402317	0	○	○
	SAND PLUGGER AND HOSE VSB	6400375	1	○	○
	SUPER BLAST 25KG	8379	1	○	○
<b>Detergent</b>					
	ALTO ACIDO 10 L	81204	1	○	○
	ALTO ACTIVE WAX 10 L	81177	1	○	○
	ALTO ALLOSIL 10 L	81237	1	○	○
	ALTO ANTI-STONE 10 L	80919	1	○	○












## Electrically heated stationary pressure washers

Accessories		Ref. no.	Min. required	SH SOLAR 7P-170/1200 E36 400/3/50 EU	SH SOLAR 7P-170/1200 E54 400/3/50 EU
	ALTO COMBI ACTIVE 10L	81172	1	○	○
	ALTO INTENSIVE 10 L	81137	1	○	○
	ALTO J 25 MULTI 10 L	80923	1	○	○
	ALTO RIMTOP 10 L	80935	1	○	○
	ALTO SAPPHIRE 10 L	81180	1	○	○
	ALTO STONE-EX 10 L	81191	1	○	○
	ALTO SUPERPLUS 10 L	81170	1	○	○
	ALTO UNIVERSAL 10 L	80930	1	○	○
	ANTI-STONE SET-6X1 L	8466	1	○	○
	AUTO ACTIVE 10 L	81136	1	○	○
<b>Brush Washing</b>					
	BRUSH INSERT	10356	1	○	○

## Electrically heated stationary pressure washers












Accessories		Ref. no.	Min. required	SH SOLAR 7P-170/1200 E36 400/3/50 EU	SH SOLAR 7P-170/1200 E54 400/3/50 EU
	WASH BRUSH - ERGO - UNIVERSAL LANCE	14202	1	<input type="radio"/>	<input type="radio"/>
	WASH BRUSH L1550 MM	6400088	1	<input type="radio"/>	<input type="radio"/>
	WASH BRUSH L2350 MM	6400087	1	<input type="radio"/>	<input type="radio"/>
<b>Special Nozzle</b>					
	NOZZLE FOR LONG LANCEJET 6-7 M	2802696	0	<input type="radio"/>	<input type="radio"/>
	NOZZLE PROTECTION CAP PA	18430	1	<input type="radio"/>	<input type="radio"/>
<b>Stationary Equipment</b>					
	ACCESSORY FROST PROTECTION DELUXE	107370955	1	<input type="radio"/>	<input type="radio"/>
	ACCESSORY FROST PROTECTION STANDARD	107370954	1	<input type="radio"/>	<input type="radio"/>
	COINBOX 0.5 EUR	54328	1	<input type="radio"/>	<input type="radio"/>
	COINBOX 0.5 EUR INCL DETERGENT	54332	1	<input type="radio"/>	<input type="radio"/>
	COINBOX 1EUR	54329	1	<input type="radio"/>	<input type="radio"/>
	COINBOX 1EUR INCL DETERGENT	54333	1	<input type="radio"/>	<input type="radio"/>
	COINBOX TOKEN	54330	1	<input type="radio"/>	<input type="radio"/>
	COINBOX TOKEN INCL DETERGENT	54334	1	<input type="radio"/>	<input type="radio"/>
	MAINS CUT OFF BUTTON	29277	1	<input type="radio"/>	<input type="radio"/>
	OPTION 1XDETERGENT SOLAR	107370952	1	<input type="radio"/>	<input type="radio"/>
	OPTION 2XDETERGENT SOLAR	107370953	1	<input type="radio"/>	<input type="radio"/>
	OPTION AUTOMATIC PRESSURE RELIEF SOLAR	107370966	1	<input type="radio"/>	<input type="radio"/>
	OPTION NO-SCALE SOLAR	107370958	1	<input type="radio"/>	<input type="radio"/>
	OPTION REMOTE CONTROL 4 BUTTONS	107340913	1	<input type="radio"/>	<input type="radio"/>
	OPTION REMOTE CONTROL 5 BUTTONS	107340914	1	<input type="radio"/>	<input type="radio"/>

## Electrically heated stationary pressure washers

Accessories		Ref. no.	Min. required	SH SOLAR 7P-170/1200 E36 400/3/50 EU	SH SOLAR 7P-170/1200 E54 400/3/50 EU
	OPTION WATER INLET SECURITY	107340910	1	○	○
	REMOTE CONTROL BOXES 2 BUTTONS	107340911	1	○	○
	REMOTE CONTROL BOXES 3 BUTTONS	107340912	1	○	○
<b>Drain and Pipe Cleaning</b>					
	DRAIN CLEANER 05 20M HOSE	6401266	1		
	DRAIN CLEANER 06 20M HOSE	6401268	1	○	○
	DRAIN NOZZLE 05 3/8	2800084	0		
	DRAIN NOZZLE 06. 3/8	2800894	1	○	○
	PIPE CLEANING HOSE 4X10M	301002490	1		
	PIPE CLEANING HOSE 4X20M	301002491	1		
	PIPE CLEANING HOSE 4X30M	301002492	1		
	PIPE CLEANING NOZZLE 1/8INC IG DN4	46921	1		
	PIPE CLEANING ROTATY NOZZLE 1/8INC IG DN	46918	0		
<b>Filter Pressure Washer</b>					














## Electrically heated stationary pressure washers











Accessories		Ref. no.	Min. required	SH SOLAR 7P-170/1200 E36 400/3/50 EU	SH SOLAR 7P-170/1200 E54 400/3/50 EU
	CARTRIDGE FILTER REPLACEM. 50 µM	1104041	1	○	○
	FILTER - WATER/SAND. SS	4601431	1	○	○
	FILTER CARTRIDGE 1 1/2	4602439	1	○	○
	SAND FILTER 50MICRON UNIVERSAL	1604461	1	○	○
<b>Non Blacking High Pressure Hose, DN10</b>					
	20 M 2 WIRE HOSE 3/8 FOOD	1401991	1	○	○
	25 M 2 WIRE HOSE 3/8 FOOD	1402007	1	○	○
	30 M 2 WIRE HOSE 3/8 FOOD	1402015	1	○	○
	HOSE DN10 10 M 2W 3/8X3/8 GRAU-FOOD	6101767	1	○	○
	HOSE DN10 15 M 2W 3/8X3/8 GRAY-FOOD	1401983	1	○	○
<b>High Pressure Hose, DN10</b>					
	2 M 2 WIRE HOSE 3/8 DN10	1402924	1	○	○
	3 M 2 WIRE HOSE 3/8 DN10	1402932	1	○	○
	5 M 2 WIRE HOSE 3/8 DN10	1402940	1	○	○














## Electrically heated stationary pressure washers

Accessories		Ref. no.	Min. required	SH SOLAR 7P-170/1200 E36 400/3/50 EU	SH SOLAR 7P-170/1200 E54 400/3/50 EU
	25 M 2 WIRE HOSE 3/8 DN10	1402080	1	○	○
	30 M 2 WIRE HOSE 3/8 DN10	1402098	1	○	○
	50 M 2 WIRE HOSE 3/8 DN10	1402759	1	○	○
	HOSE DN10 10 M 2W 3/8X3/8 INCH	6101766	1	○	○
	HP HOSE 3/8INCH 1M DN10. COMPL.	1402916	1	○	○
	HP HOSE DN10 150DEG L15000mm	1402064	1	○	○
	M 20 WIRE HOSE 3/8 DN10	1402072	0	○	○
<b>High Pressure Hose, DN8</b>					
	10 M 1 WIRE HOSE 5/16 DN8	1405569	1		
	HOSE DN8 1 WIRE 10M W.ERGO FEMALE COUPL.	101405770	1		
	HOSE DN8 1 WIRE 15M W.ERGO FEMALE COUPL.	301001100	1		
	HOSE DN8 1 WIRE 20M W.ERGO FEMALE COUPL.	301001101	1		











## Electrically heated stationary pressure washers

Accessories		Ref. no.	Min. required	SH SOLAR 7P-170/1200 E36 400/3/50 EU	SH SOLAR 7P-170/1200 E54 400/3/50 EU
	HOSE DN8 20 M 1W - 3/8X3/8	1405666	1		
<b>Ergo System Coupling and Adapter</b>					
	COUPLING - FEMALE/Q-COUPPL 3/8 INCH	106402075	1	○	○
	ERGO COUPLING KIT	101119496	1	○	○
	HIGH PRESSURE COUPLINGS KIT	101119499	1	○	○
	Nippel F. Q-COUPPL. 3/8 INCH	1600493	1	○	○
	NIPPLE F/QUICK COULING 3/8 SS	1603101	1	○	○
	NIPPLE FOR SPRAY LANCE STAN.L	1609325	0	○	○
	PACKING RING 23.8X17.2X2 3/8 INCH ST-NBR	1801075	0	○	○
<b>High Pressure Hose, DN12</b>					
	10 M 2 WIRE HOSE 1/2 DN12	4810219	0	○	○
	15 M 2 WIRE HOSE 1/2 DN12	4810213	0	○	○
	20 M 2 WIRE HOSE 1/2 DN12	4810214	0	○	○
<b>Brush Rotary</b>					










## Electrically heated stationary pressure washers

Accessories		Ref. no.	Min. required	SH SOLAR 7P-170/1200 E36 400/3/50 EU	SH SOLAR 7P-170/1200 E54 400/3/50 EU
	BRISTLE. LONG	6401431	0	○	○
	NYLON. BRISTLE FOR ROTARY	6401432	0	○	○
	ROTARY BRUSH 055 1700MM	6400019	1		
	ROTARY BRUSH 055 L800 MM	6400018	1		
	ROTARY BRUSH 065 L1700 MM	6400016	1	○	○
<b>Special Lance</b>					
	CURVED LANCE L1090 MM	6402016	1	○	○
	LANCE SINGLE 1500MM W/O NOZZLE	6401193	1	○	○
	UNDER CARRIAGE WASHER 40065	6400036	1	○	○
<b>Hose Reel</b>					
	CLEANING TROLLEY SS W/HOSE REEL FOAM IN	6401094	1	○	○
	HOSE TROLLEY UP TO 50 M 3/8	6400170	1	○	○
<b>Injector and Foam Sprayer</b>					
	03 INJECTOR COMPLETE	6401247	1	○	○

## Electrically heated stationary pressure washers











Accessories		Ref. no.	Min. required	SH SOLAR 7P-170/1200 E36 400/3/50 EU	SH SOLAR 7P-170/1200 E54 400/3/50 EU
	DETERGENT BOTTLE 2.5 L	107141635	0	○	○
	DETERGENT TANK W.SAFETY CAP - 2.5 LTR.	106403162	0	○	○
	EXTENSION HOSE 30 CM WITH ERGO COUPLINGS	301001311	0	○	○
	FOAM INJECTOR AGRESSIVE LQDS	6401245	1	○	○
	FOAM INJECTOR W BYPASS	6401242	1	○	○
	FOAM INJECTOR W BYPASS S. S	6401243	1	○	○
	FOAM INJECTOR STANDARD	6401244	1	○	○
	FOAM LANCE COMPLETE L600 MM	6404368	1	○	○
	FOAM LANCE COMPLETE L1200 MM	6404369	1	○	○
<b>Spray Gun</b>					
	ERGO 2000 STANDARD W. HOSE SWIVEL	106403122	1	○	○
	REP. KIT SWIVEL JOINT	101119484	0	○	○
	SIDE BAR COMPL.	106402110	1	○	○

## Electrically heated stationary pressure washers

Accessories		Ref. no.	Min. required	SH SOLAR 7P-170/1200 E36 400/3/50 EU	SH SOLAR 7P-170/1200 E54 400/3/50 EU
	SPRAY HANDLE W. SWIVEL LOCK	106402190	1	○	○
<b>Tornado Nozzle with Indication Ring</b>					
	NOZZLE 0530 INDICATION RING RED	101119742	1		
	NOZZLE 0680 INDICATION RING GREY	101119747	1	○	○
	NOZZLE PROTECTION F. TORNADOL.	106402425	1	○	○
<b>Short Lance</b>					
	DOUBLE LANCE W/O NOZZLE 90MM	106402150	1	○	○
	SINGLE LANCE W/O NOZZLE 90MM	106402151	1	○	○
<b>FlexoPower Lance</b>					
	FLEXOPOWER HOUSE F.NZ 1/8 OUTS. THREAD	63251	0	○	○
	FLEXOPOWER PLUS 960 BEND W/O NOZZLE	106402282	1	○	○
	FLEXOPOWER PLUS 990 BEND W/O NOZ.	106402281	1	○	○
<b>Tornado Lance</b>					
	TORNADO PLUS 630 STRAIGHT W/O NOZZLE	106403013	1	○	○
	TORNADO PLUS 1000 BEND W/O NOZZLE	106403011	1	○	○
	TORNADO PLUS 1120 BEND W/O NOZZLE	106403010	1	○	○







## Electrically heated stationary pressure washers

Accessories		Ref. no.	Min. required	SH SOLAR 7P-170/1200 E36 400/3/50 EU	SH SOLAR 7P-170/1200 E54 400/3/50 EU
	TORNADO PLUS 2080 BEND W/O NOZZLE	106403012	1	○	○
<b>Universal Lance</b>					
	UNIVERSAL PLUS 650 W/O NOZZLE STRAIGHT	106403032	1	○	○
	UNIVERSAL PLUS 1080 W/O NOZZ STRAIGHT	106403033	1	○	○
	UNIVERSAL PLUS 1560 W/O NOZZLE STRAIGHT	106403031	1	○	○
	UNIVERSAL PLUS 2060 W/O NOZZLE STRAIGHT	106403030	1	○	○
	UNIVERSAL PLUS LANCE 940 BEND W/O NOZZ	106403036	1	○	○
	UNIVERSAL PLUS LANCE 1080 BEND W/O NOZZ	106403035	1	○	○
	UNIVERSAL PLUS LANCE 1230 BEND W/O NOZZL	106403034	1	○	○
<b>PowerSpeed Vario Lance</b>					
	POWERSPEED VARIO PLUS 1090 BEND 0530	106403094	1		
	POWERSPEED VARIO PLUS 1090 BEND 0680	106403096	1	○	○
<b>Surface Cleaning Rotary</b>					
	HYDROSCRUB P400 W/O NOZZLES	106403157	0	○	○
	HYDROSCRUB P500M Ø500 W/WHEELS W/O NOZZL	106403159	0	○	○
	HYDROSCRUB S500 Ø500 W/O NOZZLES	106403158	0	○	○



## Electrically heated stationary pressure washers

Accessories		Ref. no.	Min. required	SH SOLAR 7P-170/1200 E36 400/3/50 EU	SH SOLAR 7P-170/1200 E54 400/3/50 EU
<b>High Pressure Female Coupling</b>					
	ADAPTER KEW QUICK COUPLING FEMALE 3/8	66160	0	○	○
	ADAPTER WAP GUN COUPLING FEMALE M21X1.5	66162	0	○	○
	COUPLING GEKA FEMALE - INT THREAD 3/4 IN	1718	0	○	○
<b>Hose and Connection</b>					
	NILFISK BA VALVE COMP. GEKA	106411179	0	○	○
	NILFISK BA VALVE COMP. NITO	106411178	0	○	○
	NILFISK BA VALVE WO COUPLER	106411184	0	○	○
	WATER INLET HOSE 3/4 P/	6465	0	○	○